Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC. **Well Name:** WAYZETTA 100-26 SWD

Field Name: PARSHALL Well File #: 16733

Date Incident: 2/5/2015 Time Incident: 06:32 Facility ID Number:

County: MOUNTRAIL Twp: 153 Rng: 90 Sec: 26 Qtr: NE SW

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 45 Barrels 45 Barrels 45 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/27/2015 Clean Up Concluded: 1/10/2015

Risk Evaluation:

Low

Areal Extent:

On location outside the SWD pump building.

Potential Environmental Impacts:

Low

Action Taken or Planned:

Pump was shut off stopping the release and for repairs. Vac truck and hydrovac were used to remove the free fluids and a cleanup crew will scrape and remove the affected material. Fresh material will be brought in to replace what was removed.

Wastes Disposal Location: Vac fluids put back into the SWD, Hydrovac fluids taken to Newalta and the solids will be taken to Clean Harbors at Sawyer ND.

Agencies Involved:

Updates

Date: 2/6/2015 Status: Reviewed - Assigned to Other Agency Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location according to the report. NDIC retains oversight.